



Figure W2. (A) Portion of July 30, 1939 airphoto of confluence of Senachwine Creek and northern tributary in glacial lake plain. Some reaches showed signs of alteration, but the mainstem was free flowing. Image obtained from ISGS Historical Airphoto Archive. (B) The same area in 1998. Senachwine Creek was completely altered by this time. Image is a USGS DOQ.